

# FACILITY COMPLIANCE AUDIT REPORT

# Division of Waste Management Solid Waste Section

UNIT	TYPE	<b>:</b>				diak.			e de la comp	
Lined MSWLF		LCID		YW	Transf	er X	Compos t	SLAS		COUNTY: Catawba
Closed MSWLF	1	HHW		Vhite soods	Incir	1	T&P	FIRM		PERMIT NO.: 18-08T
CDLF	1	e T&P / ollection	1 .	Tire onofill	Industr Landf		DEMO	SDTF		FILE TYPE: COMPLIANCE

Date of Audit: May 17, 2011 Date of Last Audit: August 6, 2010

# **FACILITY NAME AND ADDRESS:**

City of Hickory Transfer Station 1050 1<sup>st</sup> Avenue SW Hickory, North Carolina 28601

GPS COORDINATES: N: <u>35.73125</u> W: <u>81.35588</u>

# FACILITY CONTACT NAME AND PHONE NUMBER:

Mr. Andrew Ballentine, Solid Waste Manager (828) 323-7439 aballentine@ci.hickory.nc.us

# **FACILITY CONTACT ADDRESS:**

P.O. Box 398 Hickory, North Carolina 28601

# **AUDIT PARTICIPANTS**:

Andrew Ballentine, Solid Waste Supervisor Charles Gerstell, NCDENR, Solid Waste Section

#### STATUS OF PERMIT:

A Permit to Operate A Municipal Solid Waste Transfer Facility was issued to the City of Hickory on February 19, 2010 and shall expire on February 19, 2015

# PURPOSE OF AUDIT:

Comprehensive Audit

# **NOTICE OF VIOLATION(S):**

None

You are hereby advised that, pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Statute or Regulations. For the violation(s) noted here, you may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

# FACILITY COMPLIANCE AUDIT REPORT Division of Waste Management Solid Waste Section

Page 2 of 2

# STATUS OF PAST NOTED VIOLATIONS:

None

# **AREAS OF CONCERN AND COMMENTS:**

- 1. Facility has a service area of the City of Hickory only.
- 2. Facility receives approximately 86 tons of waste per operating day.
- 3. All waste received is taken to the Blackburn Sanitary Landfill.
- 4. Permit and Operations Plan were reviewed. Both documents were current and available for review.
- 5. Reviewed waste screening reports and appeared adequate. Unacceptable waste streams are being documented when discovered along with the actions taken to properly dispose of those waste streams.
- 6. Windblown waste was well managed at the time of inspection. No windblown waste was observed.
- 7. Floor of facility was well maintained at the time of inspection. The floor was being washed periodically at the time of inspection
- 8. No unacceptable waste streams were observed at the time of inspection.
- 9. Bait boxes have been provided around the perimeter of the facility to control vectors.
- 10. There are eight fire extinguishers available for fire control.
- 11. Both waste compactors at the facility have recently been replaced with new units.
- 12. Concrete on each side of the leachate drain located below the western compactor was observed to be weathered and was lower than the drain. This condition could prevent leachate from properly flowing into the drain. Steps must be taken to repair this condition. Until repairs are made, the area should be washed thoroughly to ensure that no leachate is left on the concrete surface after the facility closes.
- 13. A dumpster has been provided on the south side of the facility to temporarily dispose of incidental waste that deposit onto the ground during each day of operation. During the inspection, the lid to the dumpster was open while it was raining lightly. The lid on the dumpster should remain closed during periods of rain to prevent excess water from being collected with the waste.
- 14. Certified Transfer Station Operations Specialists:
  - Ronald Lewis Berry II (expires 2/22/14)
  - Doug Gentry (expires 11/3/12)
  - Chucky A. Thompson (expired 2/22/11)
  - Kenneth R. Watts (expires 2/22/14)
- 15. The facility was well operated at the time of inspection. Your efforts are appreciated.

Please contact me if you have any questions or concerns regarding this audit report.

Charles V. Gerstell
Environmental Senior Specialist
Regional Representative

Phone: (704) 235-2144.

	,				
Delivered on <u>: 5/26/11</u> by	X	Electronic Correspondence	-	US Mail	Certified No. [_]

cc: Deb Aja, Western District Supervisor